



## Ersatzteil-Rundschreiben

Bremen (Germany), September 30th, 1959

To our Authorized Borgward Dealers and Workshops

### Re. Steerings for "Isabella"

We would advise that steering columns and steering column tubes are no more supplied as single parts but in assemblies only.

Same applies to steering spindle which is available as joint worm gear and bearing.

Furthermore, please, note new part numbers:

055 110 10 12 / ZF-steering box 7157.455.101 L  
(replacing L 542 036 LR)

055 110 10 13 / ZF-steering box 7157.455.102 R  
(replacing L 542 037 RL)

ZF-steering box assemblies are replaced as following:

055 110 10 06 (ZF 7316.455.103) replacing 055 110 10 02  
055 110 10 04

055 110 10 56 (ZF 7316.455.106) replacing 055 110 10 03  
055 110 10 05

Please, make the corrections in your parts list accordingly.

Yours very truly,

**CARL F. W. BORGWARD**

G. m. b. H.

Technical Spare Parts Service

signed ppa. Grimberg

signed I. A. Kessler